

## **2003 Honda Silverwing Fuel System Recall**

Make: HONDA

Model: SILVER WING

Year: 2003

Build Dates: 2002-11-18 to 2003-02-05

NHTSA CAMPAIGN ID Number: 04V163000

Date Owner's Notified: 2004-04-16 Date Received by ODI: 2004-04-12 Date Added to Database: 2004-04-20

Manufacturer's Involved: AMERICAN HONDA MOTOR CO.

Manufacturer's Responsible for the Recall: HONDA (AMERICAN HONDA MOTOR CO.)

Manufacturer Campaign Number: P26

Component: FUEL SYSTEM, GASOLINE: STORAGE: TANK ASSEMBLY

Potential Number of Units Affected: 2497

Summary: ON CERTAIN SCOOTERS, SOME FUEL TANKS WERE IMPROPERLY MANUFACTURED AND DO NOT MEET MATERIAL STRENGTH SPECIFICATIONS.

Consequence: ENGINE VIBRATION OR RIDING ON BUMPY ROADS COULD CAUSE THESE TANKS TO CRACK AND LEAK. FUEL LEAKAGE, IN THE PRESENCE OF AN IGNITION SOURCE, CAN RESULT IN A FIRE.

Remedy: DEALERS WILL PERFORM AN INSPECTION PROCEDURE THAT IDENTIFIES DEFECTIVE FUEL TANKS. IF THE FUEL TANK FAILS THE INSPECTION, THE DEALER WILL REPLACE IT WITH AN UPDATED FUEL TANK. OWNER NOTIFICATION BEGAN DURING APRIL 16, 2004. OWNERS SHOULD CONTACT HONDA AT 1-866-784-1870.

Report Initiator: MFR Vehicles Report

Notes: CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATIONS AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).